

Istvánteleki Főműhely — the Istvántelek rail works

Budapest District IV, Hungary · 47.5461, 19.1032 · site pinned via Google Places (“Istvánteleki Főműhely”)
Old railway repair works, largely out of use; a known Hungarian urbex and filming location.

THE ANSWER

STILL STANDING

Newest public imagery: **September 2025** (12 months old as of this run). It shows the main workshop halls intact, pitched roofs complete, no demolition, scaffolding or construction activity along the perimeter. The yard is chain-link fenced and the fence line is heavily overgrown. No public street-level camera exists inside the works: **11 of 18 probe points returned nothing.**

18 probe points

7 with imagery

11 blind


newest **Sep 2025**

run 21 Sep 2026

COVERAGE — 18 POINTS, CHECKED 21 SEP 2026

PT	COORDINATES	WHERE	NEWEST IMAGE	PT	COORDINATES	WHERE	NEWEST IMAGE
A1	47.54611, 19.10323	works centre	—	B1	47.54900, 19.09900	perimeter NW	May 2024
A2	47.54500, 19.10323	yard south	—	B2	47.54430, 19.09950	museum side	—
A3	47.54720, 19.10323	yard north	—	B3	47.54500, 19.09700	Tatai ut	—
A4	47.54611, 19.10120	yard west	—	B4	47.54550, 19.10100	fence line W	—
A5	47.54611, 19.10530	yard east	Oct 2023	B5	47.54660, 19.10000	perimeter W	Sep 2025
A6	47.54450, 19.10050	yard SW	—	B6	47.54750, 19.10150	perimeter NW2	Sep 2025
A7	47.54780, 19.10580	perimeter NE	Sep 2025	B7	47.54800, 19.10250	yard NW	—
A8	47.54860, 19.10300	perimeter N	—	B8	47.54350, 19.10300	yard S2	—
A9	47.54520, 19.10650	perimeter SE	Aug 2025	B9	47.54600, 19.10750	perimeter E	Aug 2025

WHERE THE POINTS FALL



Schematic, not to scale. ● green = point with a dated public image ○ white = provider returned nothing at that point.

WHAT THE CAMERAS SHOW, AND WHERE THEY STOP



West perimeter, **September 2025**. Main workshop halls, pitched roofs complete. Chain-link fence, overgrown fence line, district-heating pipe crossing the frame. No demolition or works visible.



North-east perimeter, **September 2025**. The road runs along the yard edge; dense vegetation blocks any view of the buildings behind it.

LIMITS — READ THIS PART

- **Inside the yard there is no street-level coverage.** Halls, roundhouse area and any rolling stock are not verifiable from public cameras.
- **Nothing after September 2025 is verified.** Changes in the last 12 months would not appear here.
- **Perimeter only.** Roofs, interiors and structure behind the facade are outside what the camera sees.
- **Not an inspection, not an availability check, not a permit status.** This dossier states what public imagery documents, dated.

METHOD

Site pinned with **Google Places** before probing. **Google Street View** coverage metadata requested at 18 points across the works and its perimeter roads, then dated frames pulled at the freshest covered points. All imagery fetched **21 Sep 2026**. Coordinates and capture dates are as reported by the provider; no point is claimed covered without a dated image behind it.

A blank row means the provider returned no street-level image within range of that point. It is not proof that no image exists anywhere on the site.

One location, one dossier like this, delivered in 48 hours: \$150.

The first check on a site you are actually scouting is free. Send a name or coordinates and I will run it.
haki-2@ilands.app